



ALLFIX  **HOME**
To Make Life Easy

Electrical Parts Description	Service Charge
Non-Inverter PCB repaired	₹1800
Inverter PCB repaired	₹4500
LVT (Transformer)	₹900 ₹349 (Labour)
Replace sensor	₹350 ₹499 (Labour)
Contactors replaced	₹500 ₹499 (Labour)
Contactors Daikin/ O-General	₹1500 ₹449 (Labour)
Convert PCB with remote	₹1500
Fan Capacitor - 2.5 to 10 mfd	₹250 ₹449 (Labour)
Comp Capacitor - 25 to 60 mfd	₹400 ₹449 (Labour)
Combo Capacitor (Comp+Fan)	₹500 ₹449 (Labour)
Gas Charging Description	Service Charge
Gas Charging R-22/R32	₹2499/2799
Flair nut replaced	₹150
Copper Coil Condensor 1 ton Split	₹4000
Copper Coil Condensor 1.5 ton Split	₹4500
Copper Coil Condensor 2 ton Split	₹5000
Copper Cooling Coil (Split AC)	₹6500
Capillary and filter replaced	₹350
Compressor 0.8-1 ton	₹6500
Compressor 1.5 ton	₹7500
Compressor 2 ton	₹9200
Expansion valve replaced	₹1200
Copper Cooling Coil/Condensor Coil (Window AC)	₹5000
Replacement Compressor (1 Ton)	₹4000
Replacement Compressor (1.5 Ton)	₹4500
Replacement Compressor (2 Ton)	₹5000
Service valve replaced - 1/4	₹400
Service valve replaced - 1/2	₹400
Service valve replaced - 5/8	₹500
Copper Cooling Coil (Split AC) - 1 Ton	₹5500
Copper Cooling Coil (Split AC) - 1.5 Ton	₹6500
Copper Cooling Coil (Split AC) - 2 Ton	₹7500
Copper Cooling Coil (Split AC) O General & Mitshubishi - 1.5 Ton	₹7500
Copper Cooling Coil/Condensor Coil (Window AC) - 1 Ton	₹4500
Copper Cooling Coil/Condensor Coil (Window AC) - 1.5 Ton	₹5000
Copper Cooling Coil/Condensor Coil (Window AC) - 2 Ton	₹5500
Fuse Change in PCB	₹150 ₹299 (Labour)
Cooling coil repair with Anti-rust coating	₹899

Fan Motors Description	Service Charge
Fan motor - Split AC	₹1800 ₹499 (Labour)
Blower motor - Split AC	₹2200 ₹499 (Labour)
Blower replaced	₹1100 ₹499 (Labour)
Replace Flap/Swing Motor	₹400 ₹499 (Labour)
Motor Bearing Change	₹1000
Fan motor - Window AC	₹2600 ₹499 (Labour)
Noise issue repair	₹0 ₹499 (Labour)
Service & Installation Description	Service Charge
1 meter copper pipe set (with insulation, wire)	₹900
Split AC Wall stand	₹750
Outdoor unit reinstalled	₹799
Indoor unit reinstalled	₹699
Fastner complete set	₹200
Floor stand	₹550
Universal back plate	₹300
Lite AC service	₹499
Foam-jet AC service	₹599
AC installation	₹1499
AC uninstallation	₹699
Anti-rust spray (avoid gas leak)	₹249
Lite AC service	₹499
Drain Pipe replacement (1m)	₹100
Minor Repairs Description	Service Charge
Water Leakage Repaired- Split AC	₹719
Adjust Grill Locks	₹0 ₹349 (Labour)
Adjust pipe and tight compressor screw	₹0 ₹349 (Labour)
Connector wires replaced (1m)	₹100 ₹349 (Labour)
Tighten/ Replace Thimble	₹50 ₹349 (Labour)
External Dust/stick removal	₹0 ₹399 (Labour)
Insulation refix	₹0 ₹399 (Labour)
Drain pipe adjust	₹0 ₹399 (Labour)
Noise adjustment in motor	₹0 ₹399 (Labour)
Noise adjustment in blower	₹0 ₹399 (Labour)
Noise adjustment in cabinet	₹0 ₹399 (Labour)
Noise adjustment in swing flap	₹0 ₹399 (Labour)
Water Leakage Repaired- Window AC	₹0 ₹449 (Labour)

Other Parts Description	Service Charge
AC fan blade	₹700 ₹499 (Labour)
Grill Cover	₹1500 ₹349 (Labour)
Swing blade replaced	₹400 ₹349 (Labour)
Universal remote	₹800
Water tray	₹500 ₹200 (Labour)
Stabilizer repair	₹1500
Sleeves (per piece)	₹50
Drain pipe adjust	₹100
Insulation refix	₹100
Noise issue repair	₹0 ₹499 (Labour)
Stabilizer connection	₹0 ₹399 (Labour)